

Sanitized Copy Approved for Release 2009/11/16 : CIA-RDP89B00569R000800100018-7 TNC

DATE 2040Z 18 DEC 63

SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO 25X1 RECTOR

FROM

ACTION:

INFO :

OPS 1-12

TOR: 2121Z 18 DEC 63

PRIORITY

IN 55087

25X1

TO PRIORITY

0157

25X1

3256/181100Z/342

25X1

1. 775, 37

2. 100 PERCENT

3. REMARKS: MANY SIGNALS NOTED ON ALL RECEIVERS. OPERATION NORMAL.

25X1

1. 701, 74,, 13, 11, 50, 16, 1005, 1002.

2. 100 PERCENT

3. REMARKS: SOME SIGNALS ON ALL BANDS. OPERATION NORMAL.

25X1

25 YEAR RE-REVIEW

1. 3

2. REMARKS: NO ACTIVITY OBSERVED.

25X1

1. 4, 4, 4, 4.

2. REMARKS: NO ACTIVITY OBSERVED.

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

25X1

S E C R E T

 1057 - IN 55087

PAGE TWO


 25X1

N/A

RADIO AND NAVAIDS

VOR NOT WORKING DURING MSN. ANALYSIS IN PROGRESS. WILL GIVE REPORT  
LATER. UNIT WORKED PERFECT DURING PREFLIGHT CHECK AT 0430 LOCAL  
TODAY. 618T WAS CYCLED TO WRONG FREQ ON GROUND BEFORE TAKEOFF. WAS  
RECYCLED AT 1106Z.

BIRDWATCHER

100 PERCENT. PILOT SAID BW WAS OK. ON TWO CHECK POINTS HEAVY QRM  
PREVENTED READOUT. SOME READOUTS WERE SHORTER THAN THE NORMAL   
BELIEVE THIS DUE TO KEYING RELAY BECAUSE ALL GROUND PRE-FLIGHT TESTS  
WERE NORMAL.

END OF MSG

25X1